

uvex

Automotive Glove Matrix



LOGISTICS



FOUNDRY



PRESS SHOP



BODY SHOP



PAINT SHOP














ASSEMBLY












QUALITY CHECK










Sub Department	Goods Inwards	FLT	Packing	Despatch
Task	General Handling	General Handling	Shrink Wrap / Banding	General Handling
Key Requirements	Grip / dexterity	Grip / dexterity	Cut resistance / dexterity	Grip / dexterity
Dry Glove Solution (cut 1)	 <p>uvex phynomic foam</p>	 <p>uvex phynomic foam</p>	N/A	 <p>uvex phynomic foam</p>
Oil/Grease Solution (cut 1)	 <p>uvex phynomic XG</p>	 <p>uvex phynomic XG</p>	N/A	 <p>uvex phynomic XG</p>
Dry Glove Solution (cut 5)	 <p>uvex phynomic C5</p>	N/A	 <p>uvex phynomic C5</p>	 <p>uvex phynomic C5</p>
Oil/Grease Solution (cut 5)	 <p>uvex phynomic XG</p>	N/A	N/A	 <p>uvex C500 XG</p>










Sub Department	Furnace	Moulding	Grinding	Spot Welding
Task	Handling and loading hot/sharp parts	Trimming	Using Grinding Wheels	Handling and loading hot / sharp parts
Key Requirements	Cut and heat resistance	High level cut resistance / dexterity	Abrasion / tear easily	Heat and dexterity
uvex Glove Solution	 <p>uvex C500 foam</p>	 <p>uvex phynomic C5</p>	 <p>uvex phynomic x-foam HV</p>	 <p>uvex C500 foam</p>
uvex Arm Solution	 <p>uvex C500 sleeve</p>	N/A	N/A	 <p>uvex C500 sleeve</p>
HexArmor Solution	 <p>4061 Chrome SLT®</p>	 <p>9013 900 Series™</p>	N/A	 <p>4061 Chrome SLT®</p>







Sub Department				
Task	Stacking / Stamping	Degreasing	Handling Swarf	
Key Requirements	Cut and heat resistance / high durability	Heat and liquid resistance	Dexterity / cut and puncture resistance	
uvex Glove Solution	 <p>uvex C500 foam</p>	 <p>uvex NK 4022</p>	-	
uvex Arm Solution	 <p>uvex C500 sleeve</p>	N/A	N/A	
HexArmor Solution	 <p>4061 Chrome SLT®</p>	 <p>4062 Chrome SLT®</p>	 <p>9013 900 Series™</p>	 <p>2090x Thin Lizzie™</p>














Sub Department	Handling Metal Panels		Bonding	Riveting
Task	Moving and stacking panels		Using adhesive to apply to panels	Riveting panels to car shell
Key Requirements	High cut resistance and grip in dry and oily areas		Cut and chemical protection	Dexterity / cut resistance
uvex Glove Solution	 <p>uvex C500 foam</p>	 <p>uvex C500 wet</p>	-	 <p>uvex phynomic C5</p>
uvex Arm Solution	 <p>uvex C500 sleeve</p>	-	N/A	N/A
HexArmor Solution	 <p>9013 900 Series™</p>	-	 <p>7200</p>	 <p>9013 900 Series™</p>






Sub Department	Spray Booth	Re-Work	Cleaning
Task	Using spray guns to paint body panels	Touch up work	Degreasing parts using solvents such as white spirits
Key Requirements	Liquid and solvent protection	Dexterity and feel	Cut and liquid protection
uvex Glove Solution	 <p>uvex u-fit</p>	 <p>uvex phynomic C3</p>	-
	-	 <p>uvex phynomic C5</p>	-
HexArmor Solution	N/A	N/A	 <p>7200</p>



Sub Department	Machining	General Assembly	Trimming	Final Assembly
Task	Metalworking using powered tools	Precision work handling small parts	Body panel trimming	Chassis assembly, fastening components
Key Requirements	Cut resistance / grip and dexterity	Dexterity and feel in both dry and oily areas	High level cut resistance / dexterity	Cut resistance with dexterity
uvex Glove Solution	 <p>uvex phynomic C3</p>	 <p>uvex phynomic allround</p>	 <p>uvex phynomic C5</p>	 <p>uvex phynomic foam</p>
	 <p>uvex phynomic C5</p>	 <p>uvex phynomic XG</p>	-	 <p>uvex phynomic C5</p>
HexArmor Solution	 <p>9013 900 Series™</p>	N/A	 <p>9013 900 Series™</p>	 <p>9013 900 Series™</p>



Sub Department	Inspection	Re-work
Task	Inspecting finished parts	Touch up work
Key Requirements	Protect parts from person	Dexterity and feel
uvex Glove Solution	 <p>uvex phynomic lite</p>	 <p>uvex phynomic C3</p>
	 <p>uvex phynomic C5</p>	