



## Care and Maintenance of Safety Helmets

It is important that the your Safety Helmet is fitted correctly. It should never be too tight, too loose or irritate the skin, and any other PPE used (safety glasses, lights and earmuffs) must not compromise the safety elements of the helmet.



Clean regularly with warm water and soap and allow to air dry.



Inspect the shell, headband, suspension system and other accessories daily. Focus on finding cracks, tears, punctures, holes and any other damage.



Store your head protection away from the sun and extreme temperatures where it won't get damaged.



Avoid contact with paints, paint thinners or corrosive cleaning agents, which can weaken the shell of the helmet.



Do not drill holes in the shell and do not apply labels, or write on the helmet, unless EN testing has taken place to confirm the integrity is not compromised.



The helmet can be kept for 4 years before the first use and we recommend a useful life of 4 years. A note should be made of the date first used.

